

ITEM	PI	Status
Elog	Ila, Satogata	done
RHIC timing	Michnoff, MacKay	done
FEC	Hoff	up running
operations disks	Binello	ready, no changes from last run
database	Fu	ready, no changed from last run
RHIC green synchro	Jamilkowski	done
		checked out all 12 machines in MCR. Checkout included login, screenlock, Redhat UI, standard apps (pet, Gpm, Logview, tape, AlarmDisplay, xterm, Mozilla, Bert), printing and standard keyboard shortcuts. In addition, access to the last 3 years of logged data was tested in LogView. The one problem found on several machines was the new Synergy software designed to provide cursor/keyboard access to the comfort displays. Arthur is working on getting this working. A configuration problem at mcr5s was also resolved
MCR consoles	D'Ottavio	
		done, leave the path length in the RF configuration as zero for snake off injection setup. The number is 4160um with snake on up except the QLI by disabling most of the inputs from various systems
RHIC configuration update	Marr	checked
permit link	Trbojevic, Marr	Blam appears to have received credits appropriately (even though they were 0, as expected) from the post mortem system. An outstanding issue is the blam manager is supposed to write a file to the fill area indicating it has received credits from the post mortem server. This file appears in only one dump from January 9. No files appear from today. This will be further investigated tomorrow.
post mortem	Laster	
BLAM	Laster	running. No major changes from last run
Alarms	Nemesure	done. The kickers reacted properly during the ramp test on Tuesday. It was also demonstrated they stayed up overnight without tripping. Minor problems found which turned out to be associated with some parameters got disabled on the kickers' pet page
Abort kicker	Ahrens, Mi	working order
pet pages	Nemesure	working order
LogView	D'Ottavio	working order

Logging including pool logging	D'Ottavio	General logging/logview tested. Pool logging was also tested. However, it drained the idle time from all FEC and may not be suitable during normal operation
RHIC Injection Kicker	Fischer, Zhang	both kickers were tested at 32 kV. RhicInjection with new manager code. Acquisition is good, but statuses look wrong for ATR mode with self-trigger since 0 status is now a good status. Rob/Rob will investigate.
AtR setup including instrumentations	Brown, Tsoupas, Marr	<i>Configurations checked for pp. couldn't test the flags because they are currently fully assembled yet. Will do next week. As for BLMS, it doesn't work because of the madcado group 1 ado not working due to an update of the software after last run. Mei is investigating the problem.</i>
Tape	Marr	up and down ramp were checked. Corrector power supply autocheckup worked. Injection setup also works. Remaining issues: 1. in prep, the step of drift compensation has a bug, AI is working on it. 2. in Up ramp, the steps regarding coggings need to be modified once 9MHz cavity is commissioned
RHIC BPM	Michnoff, Satogata	discovered several new bugs in bpm timing. Released a new DSP code which fixed one of the bugs. Still performing intensive testing to see whether there are more timing problems. So far so good.
RHIC IPM	Connally, Tepikian	IPM HVs were excercised. both manager and application were tested. New features were checked. The pet page on the left has been updated to include these new features: [1] The data quality checks have been added, [2] parameters for the limits that determine the data quality checks, [3] a new parameter that estimates the central peak oscillations of the data samples and [4] functionality to adjust the bias supply voltage when the pressure changes. For the data quality numbers: Odd is bad, Even is suspect and Zero is good. The (shown at right) application is currently a work in progress showing the new trends.
RHIC WCM Electron Cloud Detector	Lee Zhang, Lee	Checked. Both wcms are running No changes during the shutdown. Will check it when HV is turned on

Schottky	Brown	Schottky systems check out ok. Managers were started and instruments are turned on. Just need beam now. Motion control was checked out by Dave Gassner. Looks good.
RHIC BLM	Bai, Neseasure	both managers were checked. Ring mode works. First turn mode doesn't work so far because the existing madc Group 1 ados are not properly configured due to a software change AI made after last run. As soon as AI fixes the madcGroup1 ado settings, we will check the firstTurn mode as well as AtR mode. A new threshold file for pp is now available. Three mismatches between gainAdo and v118Analog in RHICgddb::blm_map were found and fixed. All blm HVs are not up yet. will be checked out when all HVs are available.
RhicOrbitDisplay and orbit correction	Ptitsyn, Michnoff	RhicOrbitDisplay works. However, due to the new definition of RHIC bpm status bits, all the old orbit data are current labelled as bad bpms and the orbit correction part can't be checked out. Discussions are under going regarding what's the best approach to make the archived data valid.
RHIC chromaticity application	Tepikian	applicatin ran okay with Blue but not yellow. Investigating
RHIC Artus	Michnoff	Application checked. Tune range adjusted to 0.5-1.0. Can't fire kicker due to the vacumm work in the tunnel
Injection damper	Michnoff	Application checked with a 17KHz simulated input signal. The actual kicker high voltage PS is still LOTO'd
RHIC CNI Polarimeter	Huang, Nemesure, Gill	polarimeter target control was excercised. The communication problem between the CNI polarimeter PC and server was fixed. Both "Profile by sweep" and "Emittance measurement" in Yellow were also practised. However, the application didn't get completed because the data analysis was not analyzed by the PC. The full system testing is still in working progress.
RHIC low intensity bunch suppression	Marr, Fischer	Tested and worked properly
Bunch intensity monitor	Kuik	
RampEditor	D'Ottavio	The application was checked except the new function of ramp replay.
Online model	GRD	checked and in working order

ramp pp90	Tepikian, Marusic, Hoff, Morris, D'Ottavio, GRD	ramp was tested successfully. Issues remaining:(1) sextupole ramping rate at the end is too high. Suspect this is due to 2nd order chromaticity correction from pp83 (2) b12-DX WFG current didn't follow the design well close to the end of the ramp
drift compensation	Marusic, Morris, Hoff	tested and the correction also goes away prior to the start of the ramp. However, there is still a step with error in prep
ramp replay and revert	D'Ottavio, Hoff, Marusic	
BBQ/BtF	Minty, Wilinski, Dawson	Blue BBQ system was tested with a fixed frequency resonator in Blue H and a variable frequency resonator in Blue V. Some ad bugs were discovered and fixed. BtF was also taken with Blue V and the measurements were as expected. Yellow BBQ/BtF/tune-feedback will be checked out once the AFE is installed.
Tune/coupling feedback	Marusic, Minty	The system was successfully exercised with the Blue BBQ by modulating the V resonator about a frequency of 0.025Hz. The Yellow tune feedback yet has to be tested once the BBQ system is available.
coupling angle measurement	Yun, Beebe-Wang	Had trouble with the RHIC skew quad modulation application. Hoff and Laster re-furbished an old pet page under coupling. The pet page was then tested successfully for modulating either family2 or family1&3.
dQmin application	Beebe-Wang	Tested DQmin application. It successfully picked up the tune settings, skew quad family settings and skew quad corrections as expected. At the time of the test, the blue BBQ was running, but yellow was not. The BBQ resonator was connected to the Blue vertical. So, the DQmin application picked up the locked Blue vertical signal; random blue horizontal signal; static yellow vertical and horizontal signals. All as expected. It also picked up signals from Artus (both plans of blue and yellow). But the High frequency Schottky signals are not available. Over all DQmin runs fine
RHIC collimator	Drees, GRD	exercised both collimators. Discovered the cross-talk between the blue collimator motion and Phenix background. Found it was due to ground loop problem after some investigations. Plan is to replace a cable in Phenix.
RHIC Tune Display	D'Ottavio	Checked and adjusted the tune range for coming pp run

LISA  
Gap cleaning  
IR Bump  
plotfill

FDAView

AC dipole

RF system

D'Ottavio  
Drees, Fu  
Pilat, Binello  
Satogata

Satogata

Bai, Oddo, Wang

RF group

Checked with the new Vernier scan online analysis  
in working order

tested with BBQ

Bai tested plotfill with ramps in run08. The application works as  
expected.

Bai tested FDAView using run08 data. Application ran as expected.  
However, there is no polarization data available.

The RF signal for the ac dipole clock was restored. Exercised both  
H and V ac dipole, yet only vertical ac dipole current readback was  
available. The H ac dipole readback will be available when Brian  
reinstall the madc channel.